



RUNDE STEMLER

DIAMETER	Guide	DIAMETER	Guide	DIAMETER	Guide	DIAMETER	Guide	DIAMETER	Guide
1.5	A	5	A	10	A	20	B	50	C
2	A	5	B	10.2	A	20.5	B	55	D
2.1	A	5.1	A	10.3	A	21	B	60	D
2.3	A	5.3	A	10.5	A	22	B	60.11	D
2.5	A	5.4	A	11	A	22.5	B	65	D
2.6	A	5.5	A	11.02	B	24	B	88	D
2.7	A	5.8	A	11.5	B	25	B		
3	A	5.95	A	12	A	25.5	B		
3.1	A	6	A	12.1	A	26	B		
3.2	A	6.2	B	12.2	A	26.5	B		
3.3	A	6.3	A	12.5	A	28	B		
3.4	A	6.5	A	13	B	30	B		
3.5	A	6.8	A	13.1	B	32	C		
3.6	A	7	A	13.5	B	35	C		
3.7	A	7.2	A	14	B	40	C		
3.8	A	7.4	A	14.5	B	41	C		
4	A	7.5	A	15	B	42	C		
4.1	A	8	A	16	B	43	C		
4.2	A	8.2	A	16.5	B	45	C		
4.3	A	8.5	A	17	B	48	C		
4.4	A	8.6	A	17.6	B				
4.5	A	9	A	18	B				
4.7	A	9.2	A	19	B				
4.8	A	9.5	A	19.5	B				
4.9	A	9.75	A						



KVADRATISKE STEMLER

A	Guide
3	A
5	A
7	A
8.3	B
9	B
10	B
14.2	B
20	B
22	B



REKTANGULÆRE STEMLER

L x B	Guide	L x B	Guide
3.5 x 2.5	B	22 x 2.5	B
5x3	A	25 x 3.5	B
6 x 1.5	B	25 x 5	B
8 x 2.1	B	25 x 5.9	B
10 x 2.5	B	25 x 6	B
10 x 3	A	30 x 3.5	B
10 x 3.5	B	30 x 5	B
10 x 3.6	B	30.5 x 5.5	B
10 x 5	A	35 x 8	C
10 x 6	A	38 x 5	C
10 x 6.5	B	38 x 13.5	C
13 x 2.5	B	40 x 5	C
13 x 3	B	40.8 x 5	C
13 x 7	B	45 x 6	D
14.6 x 5.6	B	45 x 9	C
15 x 5	B	65 x 11	D
15.9x11	B	66.3 x 39.5	D
16 x 2.5	B	80 x 5	D
16 x 4	B	110x5	E
16 x 12	B	110.44x5	E
17.5 x 8	B	110.8 x 5	E
18x10	B		
20 x 3	B		
20 x 4	B		
20 x 5	B		
20 x 10.4	B		



OBRUNDE STEMLER

L x B	Guide
6x4	A
7x5	A
8x3	B
8x4	A
8x4	B
8.6 x 3.6	B
9x6	A
10 x 3	A
10 x4	A
10 x 5	A
10 x 7	B
10.1 x 3.1	B
10.3 x 6.8	B
10.5 x 3	A
12 x 4.5	B
13.3 x 5.3	B
14 x 9	B
15 x 5	B
15 x 10	B
16.5 x 4.5	B
17 x 7	B
18 x 6.5	B
19 x 8	B
20 x 2	B
20 x4	B
20 x 5	B
20 x 12	B
20 x 13	B
20 x 16	B

L x B	Guide
21 x 13	B
23 x 10	B
26 x 9	B
30 x 6	B
30 x 9	B
30 x 14	B
31 x 10	B
35 x 8	C
50 x 8	C
65.5 x 13	D
67.7x25.7	D

